

Documents obtained by the Oversight Committee depict widespread defects in fire detection systems, fire service mains, fire sprinklers, fire-proof construction materials, and electrical wiring throughout the Embassy complex. Other documents implicate the Managing Partner of First Kuwaiti, the prime contractor, in an illegal kickback scheme to obtain subcontracts under the Army's multi-billion logistical support contract.

Documents and Links

- [Letter to Secretary Rice](#)
- [October 12: State Department's Response](#)